## **SAMPLE DOCUMENT**

| 2018   | B BC  | DATEKA'   100-Point Inspection  |
|--|---|---|
| Bayliner VR6 Bown  | -10er<br>3LBX3201A818   |   |
| Engine Monstage 202 Engine ON  | SLD/3201/1010   |   |
| Engine Mercury 200 Engine SN   |   |   |
| Trailer N/A Trailer VIN  | Axles Brakes  |   |
| Engine Summary   | Visual Check  | Accessories   |
| Engine Service  300 Hour (Mercury)  100 Hour (Mercury)  Includes  Spark plugs  Engine oil & filters  Gear case fluid  Water pump/Impeller  Fuel filters  Prop shaft lube  Thermostat  Sleeve-prop bore   | Boat  Minor cosmetic issue  Fassed  N/A  Gelcoat  Emblems  Decals  Upholstery  Flooring  Windshield  Rub rail  Hardware  Pontoons  Panels | Electrical  Volt meter  Battery 1  Battery 2  Battery switch  Bilge pump(s)  Bilge blower(s)  Horn  Port nav light  Stbd nav light  Anchor /All-around light  Stern light |
| Anodes  Water separator filter  Lower unit/skeg  Date completed  Technician  Certification #   Anodes  V  Lower unit/skeg  Lower unit/s | Prop  | Stern light  Interior lights  Stereo speakers  Stereo headunit  Depth gauge/Transponder  Livewell  Display screens  |
|  | Notes on cosmetic issues  | General   |
| Run Check Engine start  Idle RPM Shifts  Motor trim/limit Engine safety cutoff Steering system Fuel gauge Oil pressure   | Cleaning & Prep  Exterior Detail  Gelcoat Buff  | Bimini top  T-top  Ski/Tow pylon  Wakeboard tower  Storage cover  Toneau/Cockpit covers  Anchor/chain  Swim ladder  Owner's manual  |
| Tachometer ✓ ☐  Leak check ✓ ☐   | Interior Detail   | Key(s) ✓ □  |

## **SAMPLE DOCUMENT**

## B BOATEKA | 100-Point Inspection

| Trailer Inspection   |  | Engine Diagnostics  |  |
|--|--|---|--|
| Tread wear acceptable Spare Acceptable level of corrosion Bow strap Bow safety hook  |  | Compression         Run History           Cylinder PSI         RPM         Hours           Cyl 1         200         0-1000   |  |
| Tongue safety chains Safety brake cable Brakes   |  | Cyl 5 4000-5000 5000-6000 6000+   |  |
| Additional Checks  |  |   |  |
| Safety Labels Prop warning - Helm Prop warning - Transom CO warning - Helm CO warning - Transom Leaking fuel No Flammables Blower label - Helm NMMA boat checklist NMMA Trailer checklist USCG capacity label Vessel HIN check Trailer VIN check | Present Replaced N/A   | Comments  Bimini has been replaced  New speakers (bow)  New battery  Final Inspection  MK  Date 1/14/2021   |  |
| Document Check Boat recall check Engine recall check Boat existing warranty Engine existing warranty   | No Issues No Issues Fixed N/A  V  V  V  V  V  V  V  V  V  V  V  V  V | This checklist is not a warranty or affirmation of fact or written promise of any kind by Boateka, Inc., Brunswick Corporation, their affiliates, agents or any other agent made in connection with the sale of the boat which relates to the nature of the material or workmanship of the boat, its engine and equipment, nor does it affirm or promise that such material or workmanship is defect-free, nor is it a warranty or guaranty that certain conditions do not exist. This checklist is purely for purposes of customer orientation and inspection and shall not expand, replace or substitute for any warranties provided by Boateka, the boat, engine, or any component manufacturer. |  |
| Date checked \ / \ / \ / a   | 2021   |   |  |